

Audio System

Posted by einsvonzehn - 2016/05/06 20:31

Hi again, still have a couple of things to fix.

After getting the radio/lights sorted out, I now have a radio and tape working BUT only out of the passenger side door, left side as mine is a RHD import from Japan which was based in Cardiff til being exported to Spain in 2006.I bought it last week.

I have a workshop manual but it appears to be for US and Canada models,the colour coding is not the same as my wiring which has 2 colours, whereas the book shows single colour wiring. Looking to the back of the radio, the multi socket pins. Are these speaker outgoing pairs vertical eg. left top FRH, left bottom FLH speakers, or paired sideways.

To give the whole story the woofer and the 2 small speakers are dead as well.

=====

Re: Audio System

Posted by einsvonzehn - 2016/05/07 11:46

Update: Having taken the door panels off, tested the speakers, all ok.

I connected another speaker to the connectors at the speakers and nothing coming.

I am thinking that whilst only the left door speaker is working, could it be the Stereo component amp at fault.

Is this located under the steering wheel panel?

But what confuses me is the woofer is not working.

This is fed from each of the audio circuits so if the left speaker is working why is nothing coming out of the woofer?

I hope someone has some tips as I dont know how I could test the Stereo Comp. amp.

Mayby one of you come up with another idea as I am no expert at audio systems. To me this seems complicated for an old car.

=====